1.1.1.

1.2.	Install SCSI PCB. Adaptec 29160 (SMART APEX ONLY)			
1.2.1.	Install the SCSI PCB in the <b>first</b> available PCI slot.			
1.3.	Update the SCSI Drivers. (SMART APEX ONLY)			
1.3.1.	Insert the BrukerCD.			
	Go to the Control Panel and select System/ Hardware/ Device manager/ SCSI and RAID controllers/SCSI Controller.			
1.3.2.	Click reinstall driver			
	Update device driver wizard	Next		
	Install hardware device driver	$(\checkmark)$ Search for a suitable driver	Next	
	Locate driver files	$(\checkmark)$ Specify a location	Next	
	Upgrade device driver wizard	Browse		
	Bruker CD Drivers/AHA29160/W2k/WIN2000	\ULTRA160\ADPU160M.INF	[Open]	
	Upgrade Device wizard	Ok		
	Digital Signature not found	[Yes]		
	Completing the Upgrade Device Driver Wizard	[Finish]		

1.3.3.

Reboot the computer and enter the SCSI Select Utility. (CNTLA) (SMART APEX ONLY)

Enter Configure/View Host Adapter Settings

Adaptec SCSI Card29160.... Properties [Close]

## 29160 Adaptec Utility v3.10.0 Configuration

## **SCSI Bus Interface Definitions**

SCSI Controller ID	7
SCSI Controller Parity	Enabled
SCSI Controller Termination	<enter></enter>
LVD/SE Connector	Enabled
SE Connector	Automatic

## **Additional Options**

Boot Device Configuration	<enter></enter>	
Select Master SCSI	29160	A at slot 02 00 10:00
Boot SCSI Controller	29160	A at slot 02 00 10:00
Boot SCSI ID	0	
Boot LUN Number	0	

SCSI Device Configuration.	<enter></enter>			
Verify the following parameters for the Apex SCSI Device ID setting #6.				
Sync Transfer Rate (MB/sec)	ASYN Important!			
Initiate Wide Negotiation	No			
Enable Disconnection	No <b>Important!</b>			
Send Start Unit Command	No			
Enable Write Back Cache	N/C			
<b>BIOS Multiple LUN Support</b>	No			
Include in BIOS Scan	Yes			
Advanced Configuration Options <enter></enter>				
Reset SCSI Bus at IC Initializati	ion Disabled			
Display <ctrl> <a> Message</a></ctrl>	E Enabled			
Extended Int 13 Translation	Disabled Important!			
POST Display Mode	Verbose			
SCSI Controller Int 13 Support	Disabled:NOT scan			
Domain Validation	Disabled			
Support Removable Disks	Disabled			
BIOS Support for Bootable CD	-ROM Enabled			
SAVE Changes Made and Exit.				

Note the correct Power-on sequence for the APEX detector. 1) Controller 2) Computer 3) APEX Power Supply.

1.4. Retrieve the version number of the SCSI NT driver. (SMART APEX ONLY) Select Windows Explorer Navigate to: C:\winnt\system32\drivers Right click on: Adpu160m.sys Select Properties Click on "Version" tab Record this version on the Serial Number Report.

NOTE:

Must reinstall EasyWriter (Adaptec) CD-ROM software to get SMART to recognize LDI SCSI driver.